

Inspection Work Order

FIELD SERVICE
Modern minimalist

WORK ORDER

WO-2026-8849

ASSET

FIRE-BOR-03

STATUS

Completed with follow-up

Report

FSR-2026-4109

Service date

2026-05-28

Customer

Mavuno Retail Group

Customer reference

CUST-MAV-2048

Site

Borrowdale Flagship Store

Site reference

SITE-BOR-001

Asset

FIRE-BOR-03 - Emergency Lighting Circuit

Priority

Planned inspection

SLA target

2026-05-28T16:00:00+02:00

Arrival / completion

2026-05-28T11:15:00+02:00 / 2026-05-28T12:50:00+02:00

Safety status

Follow-up required: one fixture dim

External system

MaintainCloud

Integration reference

INSP-FIRE-8849

Approval status

Maintenance lead reviewed

Retention class

INSPECTION-RECORD-10Y

Recommendations

Replace dim fixture within seven days and rerun night visibility test.

ENTERPRISE SERVICE CONTROLS

WORK ORDER

WO-2026-8849

TECHNICIAN ID

TECH-057

ASSET TAG

FIRE-BOR-03

SLA TARGET

2026-05-28T16:00:00+02:00

SAFETY STATUS

Follow-up required: one fixture dim

INTEGRATION REF

INSP-FIRE-8849

APPROVAL

Maintenance lead reviewed

RETENTION

INSPECTION-RECORD-10Y

SERVICE TASKS

Code

Description

Hours

Result

VISUAL

Inspect emergency lighting
fixtures and labels

0.5

One fixture dim

TEST	Run battery backup test and record duration	0.75	Passed
ACTION	Create follow-up item for dim fixture replacement	0.25	Follow-up opened

TECHNICIAN	CUSTOMER	SUPERVISOR

ENTERPRISE SERVICE BOUNDARY
Teleza renders work-order evidence from buyer-owned service systems. Scheduling, dispatch, asset authority, inventory movement, payroll, statutory inspection, and proof-of-signature remain buyer responsibilities.