

Photo Evidence Report

COMPLIANCE REPORT
Executive summary

RESULT

Before/after evidence packet ready for client review

STATUS

Evidence captured

NEXT REVIEW

2026-06-08

Report	SW-PHOTO-2026-0421
Report date	2026-05-25
Site	Riverside Commerce Park
Inspector	A. Moyo
Permit	NPDES-ZW-7781
Location	North yard evidence set
Site reference	
Program	
Regulatory scope	
Risk rating	
Integration reference	
Retention class	

COMPLIANCE CONTROLS

SITE Riverside Commerce Park	PERMIT NPDES-ZW-7781
INSPECTOR A. Moyo	NEXT REVIEW 2026-06-08

FINDINGS AND CORRECTIVE ACTIONS

Area	Observation	Severity	Action	Photo
North drainage channel	Before photo: sediment buildup at outlet screen	Medium	Attach paired after photo once outlet screen is cleared	SW-IMG-421-A-BEFORE
North drainage channel	After photo: outlet screen cleared and sediment removed	Low	Archive as remediation evidence for weekly client packet	SW-IMG-421-A-AFTER
Loading apron	Absorbent applied to oil sheen near catch basin	Medium	Capture follow-up photo after absorbent is collected	SW-IMG-421-C

INSPECTOR	SITE OWNER	CORRECTIVE ACTION OWNER

CORRECTIVE ACTION CONTROL

Severity, action owner, photo reference, source-system reference, retention class, and next review fields are designed to support audit follow-up rather than a one-off inspection note. Teleza renders the packet; the buyer remains responsible for compliance decisions and statutory certification.