

Site Survey Report

FIELD SERVICE
Dense operational

WORK ORDER

WO-2026-8846

ASSET

SURV-BOR-ENTRY

STATUS

Survey completed

Report	FSR-2026-4106
Service date	2026-05-28
Customer	Mavuno Retail Group
Customer reference	CUST-MAV-2048
Site	Borrowdale Flagship Store
Site reference	SITE-BOR-001
Asset	SURV-BOR-ENTRY - Entrance Sensor Upgrade
Priority	Project discovery
SLA target	2026-05-28T14:00:00+02:00
Arrival / completion	2026-05-28T09:30:00+02:00 / 2026-05-28T11:45:00+02:00
Safety status	Ladder work not required
External system	InstallFlow
Integration reference	SURV-BOR-8846
Approval status	Survey reviewed
Retention class	PROJECT-RECORD-7Y
Recommendations	Proceed with sensor upgrade after confirming ceiling cable route and after-hours access window.

ENTERPRISE SERVICE CONTROLS

WORK ORDER WO-2026-8846	TECHNICIAN ID TECH-071
ASSET TAG SURV-BOR-ENTRY	SLA TARGET 2026-05-28T14:00:00+02:00
SAFETY STATUS Ladder work not required	INTEGRATION REF SURV-BOR-8846
APPROVAL Survey reviewed	RETENTION PROJECT-RECORD-7Y

SERVICE TASKS

Code	Description	Hours	Result
MEASURE	Measure entrance width and verify mounting surface	0.75	Completed

NETWORK	Confirm network point, power location, and cable route	0.75	Completed
RISK	Record access constraints and customer operating hours	0.5	Documented

TECHNICIAN	CUSTOMER	SUPERVISOR
_____	_____	_____

ENTERPRISE SERVICE BOUNDARY
Teleza renders work-order evidence from buyer-owned service systems. Scheduling, dispatch, asset authority, inventory movement, payroll, statutory inspection, and proof-of-signature remain buyer responsibilities.