

# Maintenance Visit Report

FIELD SERVICE  
Modern minimalist

WORK ORDER

**WO-2026-8842**

ASSET

**GEN-BOR-02**

STATUS

**Completed**

Report

FSR-2026-4102

Service date

2026-05-28

Customer

Mavuno Retail Group

Customer reference

CUST-MAV-2048

Site

Borrowdale Flagship Store

Site reference

SITE-BOR-001

Asset

GEN-BOR-02 - Backup Generator

Priority

Planned

SLA target

2026-05-28T15:00:00+02:00

Arrival / completion

2026-05-28T10:00:00+02:00 / 2026-05-28T13:20:00+02:00

Safety status

Lockout checklist completed

External system

MaintainCloud

Integration reference

MNT-GEN-8842

Approval status

Maintenance lead reviewed

Retention class

SERVICE-RECORD-7Y

Recommendations

Replace fuel filter at next scheduled service and keep weekly run-test cadence.

## ENTERPRISE SERVICE CONTROLS

WORK ORDER

**WO-2026-8842**

TECHNICIAN ID

**TECH-057**

ASSET TAG

**GEN-BOR-02**

SLA TARGET

**2026-05-28T15:00:00+02:00**

SAFETY STATUS

**Lockout checklist completed**

INTEGRATION REF

**MNT-GEN-8842**

APPROVAL

**Maintenance lead reviewed**

RETENTION

**SERVICE-RECORD-7Y**

## SERVICE TASKS

| Code  | Description                                            | Hours | Result |
|-------|--------------------------------------------------------|-------|--------|
| CHECK | Inspect oil, coolant, battery, and visible leak points | 1.0   | Passed |

|         |                                                        |      |           |
|---------|--------------------------------------------------------|------|-----------|
| RUNTEST | Run generator under test load and record stable output | 1.25 | Completed |
| CLEAN   | Clean intake vents and update service tag              | 0.5  | Completed |

|            |          |            |
|------------|----------|------------|
| TECHNICIAN | CUSTOMER | SUPERVISOR |
| <hr/>      | <hr/>    | <hr/>      |

**ENTERPRISE SERVICE BOUNDARY**  
Teleza renders work-order evidence from buyer-owned service systems. Scheduling, dispatch, asset authority, inventory movement, payroll, statutory inspection, and proof-of-signature remain buyer responsibilities.