

Technician Timesheet Report

FIELD SERVICE
Modern minimalist

WORK ORDER

WO-2026-8841

ASSET

MULTI-BOR-OPS

STATUS

Submitted for approval

Report	FSR-2026-4105
Service date	2026-05-28
Customer	Mavuno Retail Group
Customer reference	CUST-MAV-2048
Site	Borrowdale Flagship Store
Site reference	SITE-BOR-001
Asset	MULTI-BOR-OPS - Service Visit Bundle
Priority	Daily route
SLA target	2026-05-28T18:00:00+02:00
Arrival / completion	2026-05-28T09:10:00+02:00 / 2026-05-28T15:05:00+02:00
Safety status	No lost-time incident
External system	WorkforceTime
Integration reference	TIME-TECH-042-20260528
Approval status	Pending service manager approval
Retention class	WORKFORCE-RECORD-5Y
Recommendations	Review travel allocation against route plan before payroll export.

ENTERPRISE SERVICE CONTROLS

WORK ORDER WO-2026-8841	TECHNICIAN ID TECH-042
ASSET TAG MULTI-BOR-OPS	SLA TARGET 2026-05-28T18:00:00+02:00
SAFETY STATUS No lost-time incident	INTEGRATION REF TIME-TECH-042-20260528
APPROVAL Pending service manager approval	RETENTION WORKFORCE-RECORD-5Y

SERVICE TASKS

Code	Description	Hours	Result
HVAC	HVAC controller repair and verification	3.5	Completed
LABEL	Shelf label printer repair	2.05	Completed

ADMIN	Customer update, documentation, and closeout notes	0.65	Submitted
-------	--	------	-----------

TECHNICIAN	CUSTOMER	SUPERVISOR

ENTERPRISE SERVICE BOUNDARY
Teleza renders work-order evidence from buyer-owned service systems. Scheduling, dispatch, asset authority, inventory movement, payroll, statutory inspection, and proof-of-signature remain buyer responsibilities.